


# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <b>10047</b> Accredited to ISO/IEC 17025:2017	<b>GTB Castle Limited</b>  <b>Issue No: 005    Issue date: 01 November 2023</b>	
	<b>Unit 88</b> <b>Pembroke Centre</b> <b>Cheney Manor Industrial Estate</b> <b>Swindon</b> <b>Wiltshire</b> <b>SN2 2PQ</b>	<b>Contact: Colin Newman</b> <b>Tel: +44 (0) 7714 699 926</b> <b>Fax: +44 (0) 793 486 321</b> <b>E-Mail: <a href="mailto:colinnewman@gtbcastle.com">colinnewman@gtbcastle.com</a></b> <b>Website: <a href="https://www.gtbcastleltd.co.uk/">https://www.gtbcastleltd.co.uk/</a></b>
<b>Calibration performed by the Organisation at the locations specified</b>		

### Locations covered by the organisation and their relevant activities

#### Site activities:

Location details	Activity
The customers' site or premises must be suitable for the nature of the particular calibrations undertaken and will be the subject of contract review arrangements between the laboratory and the customer.	Rotational speed Temperature Time



Accredited to  
ISO/IEC 17025:2017

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**GTB Castle Limited**

**Issue No:** 005    **Issue date:** 01 November 2023

**Calibration performed by the Organisation at the locations specified**

**Calibration and Measurement Capability (CMC)**

Measured Quantity Instrument or Gauge	Range	Expanded Measurement Uncertainty ( $k = 2$ )	Remarks	Location Code
TEMPERATURE Thermal performance of centrifuges	0 °C to 40 °C	0.50 °C		Site
ROTATIONAL SPEED Centrifuges with viewport	100 rpm to 21000 rpm	4.5 rpm		Site
TIME INTERVAL Timers associated with centrifuges	0 s to 5 hr	0.30 s		Site
<u>Methods:</u> All measurements are performed by direct comparison with the indication from a calibrated reference instrument.				
END				



Accredited to  
ISO/IEC 17025:2017

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**GTB Castle Limited**

**Issue No:** 005    **Issue date:** 01 November 2023

**Calibration performed by the Organisation at the locations specified**

**Appendix - Calibration and Measurement Capabilities**

**Introduction**

The definitive statement of the accreditation status of a calibration laboratory is the Accreditation Certificate and the associated Schedule of Accreditation. This Schedule of Accreditation is a critical document, as it defines the measurement capabilities, ranges and boundaries of the calibration activities for which the organisation holds accreditation.

**Calibration and Measurement Capabilities (CMCs)**

The capabilities provided by accredited calibration laboratories are described by the Calibration and Measurement Capability (CMC), which expresses the lowest measurement uncertainty that can be achieved during a calibration. If a particular device under calibration itself contributes significantly to the uncertainty (for example, if it has limited resolution or exhibits significant non-repeatability) then the uncertainty quoted on a calibration certificate will be increased to account for such factors.

The CMC is normally used to describe the uncertainty that appears in an accredited calibration laboratory's schedule of accreditation and is the uncertainty for which the laboratory has been accredited using the procedure that was the subject of assessment. The measurement uncertainty is calculated according to the procedures given in the GUM and is normally stated as an expanded uncertainty at a coverage probability of 95 %, which usually requires the use of a coverage factor of  $k = 2$ . An accredited laboratory is not permitted to quote an uncertainty that is smaller than the published measurement uncertainty in certificates issued under its accreditation.

**Expression of CMCs - symbols and units**

It should be noted that the percentage symbol (%) represents the number 0.01. In cases where the measurement uncertainty is stated as a percentage, this is to be interpreted as meaning percentage of the measurand. Thus, for example, a measurement uncertainty of 1.5 % means  $1.5 \times 0.01 \times q$ , where  $q$  is the quantity value.

The notation  $Q[a, b]$  stands for the root-sum-square of the terms between brackets:  $Q[a, b] = [a^2 + b^2]^{1/2}$