

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 0339 Type C Inspection Body Accredited to ISO/IEC 17020:2012	Speedy Asset Services Ltd trading as Lloyds British National Contracts	
	Issue No: 014 Issue date: 08 November 2025	
Unit 1 Regus House 84 Salop Street Wolverhampton WV3 0SR United Kingdom	Contact: Jayne Mason Tel: +44 (0)121 323 5566 Fax: +44(0)121 506 4646 E-Mail: jayne.mason@speedyservices.com Website: www.lloydsbritish.com	
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code
Address Chase House 16 The Parks Newton-le-Willows Merseyside WA12 0JQ	Head Office	A
Address Unit 1 Regus House 84 Salop Street Wolverhampton WV3 0SR United Kingdom	Inspection	B



0339

Type C Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Speedy Asset Services Ltd trading as Lloyds British National Contracts

Issue No: 014 **Issue date:** 08 November 2025

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Powered and manual lifting machines, equipment, and accessories. Excluding Tower Cranes	In-service inspection	Lifting Operations and Lifting Equipment Regulations 1998, (LOLER) SI No. 2307 Provision and Use of Work Equipment Regulations 1998, (PUWER) SI No. 2306	B
Fall arrest systems. Fixed and removable ladders, Anchor Points, Climbing and Fall Arrest PPE, Excluding PFPS	In-service inspection	Provision and Use of Work Equipment Regulations 1998, (PUWER) SI No. 2306 Work at Height Regulations 2005 SI 2005 No. 735	B
Minor Pressure Systems	In-service inspection Creation and validation of WSE Inspection of repairs and Modifications	The Pressure Systems Safety Regulations 2000. Statutory Instrument 2000 No 128 In-House Procedures and Scopes of examination	B
Intermediate Pressure Systems	In-service inspection Creation and validation of WSE Inspection of repairs and modifications	The Pressure Systems Safety Regulations 2000. Statutory Instrument 2000 No 128 In-House Procedures and Scopes of examination	B
END			