### **Schedule of Accreditation**

issued by

### **United Kingdom Accreditation Service**

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK



9208 Type C Inspection Body

**BN43 5FG** 

**GBR** 

Accredited to ISO/IEC 17020:2012

### **Ricardo Certification Ltd**

Issue No: 013 Issue date: 31 August 2023

Shoreham Technical Centre Contact: Mr Mark Dodsworth
Old Shoreham Road Tel: +44 (0)1904 404725

Shoreham-by-Sea E-Mail: mark.dodsworth@ricardo.com

Website: <a href="https://rail.ricardo.com/independent-assurance/certification/ricardo-certification">https://rail.ricardo.com/independent-assurance/certification/ricardo-certification</a>

#### Locations where inspection activities covered by the above Accreditation Standard are undertaken

Location	Activity	Location Code
5 Pinnacle Way Pride Park Derby DE24 8ZS	Head Office Control of Policy	A
Room 1302 Shun Tak Tower No 1 Xiangheyuan Street Dongcheng District Beijing 100028 PR China	Inspection Activities:	В
Palm Tower, Block B, 15th Floor, P.O Box 220048 West Bay Doha, State of Qatar	Inspection Activities:	С
Office 707 7th Floor Block B, Business Village PO Box 35173 Dubai United Arab Emirates	Inspection Activities:	D
Scale Office 3rd Floor 3412 Ath Thumanah Road 6628 Riyadh Kingdom of Saudi Arabia 13315	Inspection Activities:	E

Assessment Manager: GH Page 1 of 5



### **Schedule of Accreditation** issued by

## United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

### **Ricardo Certification Ltd**

Issue No: 013 Issue date: 31 August 2023

#### **DETAIL OF ACCREDITATION**

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Essential Requirements	Location Code
EU Regulation No. 402/2013 Implementing Article 6 (3) a of Directive 2004/49/EC - On Common Safety Method for risk evaluation and assessment.	Command Control and Signalling	Independent assessment of the application of the risk management process	402/2013/EC Annex I	A, B
EU Regulation No. 402/2013 Implementing Article 6 (3) a of Directive 2004/49/EC - On Common Safety Method for risk evaluation and assessment.	Energy	Independent assessment of the application of the risk management process	402/2013/EC Annex I	A, B
EU Regulation No. 402/2013 Implementing Article 6 (3) a of Directive 2004/49/EC - On Common Safety Method for risk evaluation and assessment.	Infrastructure	Independent assessment of the application of the risk management process	402/2013/EC Annex I	A, B
EU Regulation No. 402/2013 Implementing Article 6 (3) a of Directive 2004/49/EC - On Common Safety Method for risk evaluation and assessment.	Rolling Stock	Independent assessment of the application of the risk management process	402/2013/EC Annex I	A, B, C

Assessment Manager: GH Page 2 of 5



### **Schedule of Accreditation** issued by

### United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

### **Ricardo Certification Ltd**

Issue No: 013 Issue date: 31 August 2023

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Essential Requirements	Location Code
EU Regulation No. 402/2013 Implementing Article 6 (3) a of Directive 2004/49/EC - On Common Safety Method for risk evaluation and assessment.	Organisational	Independent assessment of the application of the risk management process	402/2013/EC Annex I	Α
EU Regulation No. 402/2013 Implementing Article 6 (3) a of Directive 2004/49/EC - On Common Safety Method for risk evaluation and assessment.	Operational	Independent assessment of the application of the risk management process	402/2013/EC Annex I	A
Independent Safety Assessment	Command Control and Signalling	Independent Safety Assessment	Ricardo defined process CENELEC standards EN 50126-1:2017 EN 50126-2:2017 EN50128:2011+A2:2020 EN 50129:2018 EN50159:2010+A1:2020	A, B, C, D, E

Assessment Manager: GH Page 3 of 5



### **Schedule of Accreditation** issued by

## United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

### **Ricardo Certification Ltd**

Issue No: 013 Issue date: 31 August 2023

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Essential Requirements	Location Code
Independent Safety Assessment	Energy	Independent Safety Assessment	Ricardo defined process CENELEC standards EN 50126-1:2017 EN 50126-2:2017 EN50128:2011+A2:2020 EN 50129:2018 EN50159:2010+A1:2020	A, B, E
Independent Safety Assessment	Infrastructure	Independent Safety Assessment	Ricardo defined process CENELEC standards EN 50126-1:2017 EN 50126-2:2017 EN50128:2011+A2:2020 EN 50129:2018 EN50159:2010+A1:2020	A, B, D, E
Independent Safety Assessment	Rolling Stock	Independent Safety Assessment	Ricardo defined process CENELEC standards EN 50126-1:2017 EN 50126-2:2017 EN50128:2011+A2:2020 EN 50129:2018 EN50159:2010+A1:2020	A, C, D, E

Assessment Manager: GH Page 4 of 5



### **Schedule of Accreditation** issued by

# United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

### **Ricardo Certification Ltd**

Issue No: 013 Issue date: 31 August 2023

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Essential Requirements	Location Code
Independent Safety Assessment	Organisational	Independent Safety Assessment	Ricardo defined process CENELEC standards EN 50126-1:2017 EN 50126-2:2017 EN50128:2011+A2:2020 EN 50129:2018 EN50159:2010+A1:2020	A, D, E
Independent Safety Assessment	Operational	Independent Safety Assessment	Ricardo defined process CENELEC standards EN 50126-1:2017 EN 50126-2:2017 EN50128:2011+A2:2020 EN 50129:2018 EN50159:2010+A1:2020	A, D, E
END				

Assessment Manager: GH Page 5 of 5