


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>0063</p> <p>Type B Inspection Body Accredited to ISO/IEC 17020:2012</p>	Inspection Services a Division of Phillips 66 Limited	
	Issue No: 025 Issue date: 30 April 2026	
Humber Refinery South Killingholme Immingham North East Lincolnshire DN40 3DW	Contact: Mr Jordan Spreckley Tel: +44 (0)1469 555407 E-Mail: jordan.l.spreckley@p66.com Website: http://www.phillips66.co.uk	
Inspection performed at / from the specified locations		

Location details	Activity	Location code
Humber Refinery South Killingholme Immingham North East Lincolnshire DN40 3DW	Contact Jordan Spreckley	Non-statutory vessels and pipe work Mechanical Integrity assessment Atmospheric storage tanks
Immingham Pipeline Centre (IPC) & Immingham Propylene Storage (IPS) West Riverside Road Immingham Dock Immingham DN40 2PD	Contact Jordan Spreckley	Non-statutory vessels and pipe work Atmospheric storage tanks
Tetney Oil Terminal Tetney Lock Road Tetney North East Lincolnshire DN36 5SR	Contact Jordan Spreckley	Non-statutory vessels and pipe work Atmospheric storage tanks
Gas Caverns Immingham LPG Gas Caverns South Killingholme	Contact Jordan Spreckley	Non-statutory vessels and pipe work



0063

Type B
Inspection Body
Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Inspection Services a Division of Phillips 66 Limited

Issue No: 025 Issue date: 30 April 2026

Inspection performed at/from main address only

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Non-statutory vessels and pipe work	In-service inspections	Provision and Use of Work Equipment Regulations SI 1998 No.2306	A, B, C, D
Mechanical Integrity assessment	RBI and fitness for service calculations	580/581 API510 API570 API579	A, B, C
Atmospheric storage tanks	In-service inspection	API653 EEMUA 159	A
END			