

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK



0191

**Type C
Inspection Body**

Accredited to
ISO/IEC 17020:2012

Asbestos Consultants Europe Ltd (trading as ACE)

Issue No: 020 **Issue date:** 13 September 2024

11 Magnet Point Estate,
Magnet Road,
Grays,
Essex,
RM20 4DR

Contact: Mr B Angell-James
Tel: +44 (0)1375 366 777
E-Mail: Ben.Angell-James@aceconsultants.co.uk
Website: www.aceconsultants.co.uk

Inspection performed at/from the locations specified below

Locations covered by the organisation and their relevant activities

<u>Location details</u>	<u>Activity</u>	<u>Location code</u>
<p><u>Address</u> 11 Magnet Point Estate, Magnet Road, Grays, Essex, RM20 4DR</p> <p><u>Local contact</u> Mr B Angell-James Tel: +44 (0)1375 366 777 E-Mail: Ben.Angell-James@aceconsultants.co.uk</p>	<p>Asbestos: Surveying</p>	<p>A</p>
<p><u>Address</u> Borough Park 1 Romney Avenue Lockleaze Bristol BS7 9ST</p> <p><u>Local contact</u> Mr J Reeves Tel: +44 (0)117 952 7609 Email: jake.reeves@aceconsultants.co.uk</p>	<p>Asbestos: Surveying</p>	<p>B</p>



0191
Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Asbestos Consultants Europe Ltd (trading as ACE)

Issue No: 020 **Issue date:** 13 September 2024

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for Asbestos in Premises	Management survey: (domestic, commercial & industrial premises)	Health and Safety Executive Asbestos: The Survey Guide (HSG 264, 2012) Documented In-House procedure as per In-House Inspection Method QOP01	A, B
	Refurbishment and demolition survey: (domestic, commercial & industrial premises)	Documented In-House procedure as per In-House Inspection Method QOP01	A, B
	Priority assessment (domestic, commercial & industrial premises)	Documented In-House procedure as per In-House Inspection Method QOP01 (based on guidance documented in Health and Safety Executive guides HSG 264 (2012) and Appx. 3 of HSG 227 (2004))	A, B
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method QOP01 (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B
END			