## **Schedule of Accreditation**

issued by

# **United Kingdom Accreditation Service**

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK



0197 Type C Inspection Body

Accredited to ISO/IEC 17020:2012

### **Environtec Ltd**

Issue No: 034 Issue date: 28 November 2024

Environtec House Contact: Mr B Arnold
The Street Tel: +44 (0)1245 381900

Hatfield Peverel E-Mail: enquiries@environtec.com
Chelmsford Website: www.environtec.com

Essex CM3 2EJ

Inspection performed at/from the locations specified below

### Locations covered by the organisation and their relevant activities

Location details		Activity	Location code
Address Environtec House The Street Hatfield Peverel Chelmsford Essex CM3 2EJ	Local contact Mr Ben Arnold Tel: +44(0)1245 381900	Asbestos: Surveying	A
Address Construction House Hermitage Way Mansfield Nottingham NG18 5ES	Local contact Mr Chris Falato Tel: +44 (0)1623 757189	Asbestos: Surveying	В
Address Second Floor Unit 3 Cadzow Park 82 Muir Street Hamilton ML3 6BJ	Local contact Ms Stephanie Kenny Tel: +44 (0)1698 421898	Asbestos: Surveying	С
Address Unit 2 Riverside Business Studios Amethyst Road Newcastle Business Park NE4 7YL	Local contact Mr Adam Ladd Tel: +44(0)1914 873 236	Asbestos: Surveying	D
Address 5a Turner Street Newport South Wales NP19 7BA	Local contact Mr David Atherton Tel: +44(0)1633 262 922	Asbestos: Surveying	E

Assessment Manager: WB Page 1 of 2



0197 Type C Inspection Body

Accredited to ISO/IEC 17020:2012

## **Schedule of Accreditation** issued by United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

#### **Environtec Ltd**

Issue No: 034 Issue date: 28 November 2024

Inspection performed by the Organisation at/from the locations specified

### **DETAIL OF ACCREDITATION**

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code	
Surveying for asbestos in premises		Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012)		
	Management survey: (domestic, commercial and industrial premises)	Documented In-House Inspection Method in Procedures Manual ETP 002	A, B, C, D, E	
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented In-House Inspection Method in Procedures Manual ETP 002	A, B, C, D, E	
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method in Procedures Manual ETP 002 (based on guidance documented in Appendix 5 of HSG 227 (2004)	A, B, C, D, E	
END				

Assessment Manager: WB Page 2 of 2