


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 0291 Type C Inspection Body Accredited to ISO/IEC 17020:2012	Bradley Environmental Consultants Ltd	
	Issue No: 017 Issue date: 23 June 2025	
	20 Stourbridge Road Halesowen West Midlands B63 3US	Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code
Address 20 Stourbridge Road Halesowen West Midlands B63 3US Local contact Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	<u>Support Functions:</u> Quality Management including document control, auditing and quality control <u>Asbestos:</u> Surveying	A
Address Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD Local contact Mr R Bridgewater Tel: +44 (0)1924 274777 Fax: +44 (0)1924 283620 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	<u>Asbestos:</u> Surveying	B
Address North West Office Constellation House Lockheed Court Amy Johnson Way Blackpool FY4 2RN Local contact Mr R Bridgewater Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	<u>Asbestos:</u> Surveying	C
Address Unit 11 Geddes House Kirkton Road North Livingston EH54 6GU Local contact Mr R Bridgewater Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Hygiene and Health	F



0291

Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd

Issue No: 017 Issue date: 23 June 2025

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264:2012) Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual	A, B, C, F
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual	A, B, C, F
	Re-inspection of identified or suspected asbestos containing material in surveyed premises	Documented in-house procedure - Inspection, section 20 and appendix 6, Quality Manual (based on guidance documented in Inspection, Appendix 5 of HSG 227 (2004))	A, B, C, F
END			