

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK



0349

Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

G&L Consultancy Limited

Issue No: 020

Issue date: 18 November 2025

Unit 5a
Chelston Business Park
Castle Road
Wellington
Somerset
TA21 9JQ

Contact: Mr D Alway
Tel: +44 (0)1823 443898
Fax: +44 (0)1823 443154
E-Mail: darren.alway@gnl.org.uk
Website: www.gnl.org.uk

Inspection performed at/from the locations specified below

Locations covered by the organisation and their relevant activities

<u>Location details</u>		<u>Activity</u>	<u>Location code</u>
<u>Address</u> 54A Huntly Road Banbridge Co. Down Northern Ireland BT32 3UA	<u>Local contact</u> Mr A Lewis Tel: +44 (0)2840 623566 Fax: +44 (0)2840 629217 Email: alan.lewis@gnl.org.uk Website: www.gnl.org.uk	Asbestos: Surveying (Office location)	C
<u>Address</u> Unit 5a Chelston Business Park Castle Road Wellington Somerset TA21 9JQ	<u>Local contact</u> Mr D Alway Tel: +44 (0)1823 443898 Fax: +44 (0)1823 443154 Email: darren.alway@gnl.org.uk Website: www.gnl.org.uk	Asbestos: Surveying (Office location)	A

Site activities performed away from the locations listed above:

<u>Location details</u>	<u>Activity</u>	<u>Location code</u>
Premises including Domestic, Commercial and Industrial	Asbestos Surveying	B



0349

**Type C
Inspection Body**

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

G&L Consultancy Limited
Issue No: 020 Issue date: 18 November 2025

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial & industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012) Documented in-house procedure Inspection Method M5	A, B, C
	Refurbishment and demolition survey: (domestic, commercial & industrial premises)	Documented in-house procedure Inspection Method M5	A, B, C
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method M5 (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B, C
END			