Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

0368

Type C Inspection Body

Accredited to ISO/IEC 17020:2012

Tersus Consultancy Ltd

Issue No: 039 **Issue date:** 28 October 2026

Suite 13 Phoenix House
Christopher Martin Road
Basildon
SS14 3EZ

Contact: Mr C Simmonite
Tel: +44 (0) 1909 560673
E-Mail: craig.simmonite@marlowe-es.com
Website: www.tersusgroup.co.uk

Inspection performed at/from the locations specified below

Locations covered by the organisation and their relevant activities

Location details		Activity	Location code
Address Suite 13 Phoenix House Christopher Martin Road Basildon SS14 3EZ	**Local contact** Mr T Rose Tel: +44 (0)1708 555705 Email: Trevor.Rose@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	A
Address Unit 1 Manor Drive Outgang Lane Dinnington Sheffield S25 3QU	**Local contact** Mrs G Purewal Tel: +44 (0)1909 560673 Email: Gurpreet.Purewal@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	B
Address Eurosafe House Tribune Way Centurion Park Clifton Moor York YO30 4RY	**Local Contact** Ms J Ormshaw Tel: +44 (0) 1904 691515 Email: Jen.Ormshaw@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	C
Address Red Mill House Red Mill Estate Wednesbury WS10 0NN	**Local contact** Mrs G Purewal Tel: +44 (0)121 244 1828 Email: gurpreet.Purewal@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	D

0368

Type C Inspection Body

Accredited to ISO/IEC 17020:2012

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Tersus Consultancy Ltd

Issue No: 039 **Issue date:** 28 October 2026

Inspection performed by the Organisation at/from the locations specified

Location details		Activity	Location code
Address Axys House Parc Nantgarw Cardiff CF15 7TW	**Local contact** Mr C Jones Tel: +44 (0) 1278 654 345 Email: Craig.Jones@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	F
Address Health Physics R S R L Building D60 Winfrith Dorchester DT2 8WQ	**Local contact** Mr J Sigsworth Tel: +44 (0) 1278 654 345 Email: James.Sigsworth@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	G
Address 10 Rutherford Avenue Didcot OX11 0DF	**Local contact** Mr J Sigsworth Tel: +44 (0) 1278 654 345 Email: James.Sigsworth@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	H
Address Hinkley Point A Power Station Bridgewater TA5 1YA	**Local contact** Mr J Sigsworth Tel: +44 (0) 1278 654 345 Email: James.Sigsworth@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	I
Address Dungeness A Power Station Romney Marsh TN29 9PP	**Local contact** Mr J Sigsworth Tel: +44 (0) 1797 343 217 Email: James.Sigsworth@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	J

0368

Type C Inspection Body

Accredited to ISO/IEC 17020:2012

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Tersus Consultancy Ltd

Issue No: 039 **Issue date:** 28 October 2026

Inspection performed by the Organisation at/from the locations specified

Location details		Activity	Location code
Address Oldbury Power Station Oldbury Naite Thornbury BS35 1RQ	**Local contact** Mr J Sigsworth Tel: +44 (0) 7914 668960 Email: James.Sigsworth@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	K
Address Berkeley Power Station Berkeley GL13 9PA	**Local contact** Mr J Sigsworth Tel: +44 (0) 7921 511 417 Email: James.Sigsworth@marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	L
Address 2 Moor Lane Highburton Huddersfield HD8 0QS	**Local contact** Ms J Ormshaw Tel: +44 (0) 1484 604920 Email: Jen.Ormshaw@ marlowe-es.com Website: www.tersusgroup.co.uk	Asbestos: Surveying	M

0368

Type C Inspection Body

Accredited to ISO/IEC 17020:2012

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Tersus Consultancy Ltd

Issue No: 039 **Issue date:** 28 October 2026

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises		Health and Safety Executive Asbestos: The survey guide (HSG264, 2012)	A, B, C, D, F, G, H, I, J, K, L
	Management survey:	Documented in-house procedure GDP1 and MGDP1	
	Domestic premises		A, B, C, D, F, G, H, I, J, K, L, M
	Commercial premises		A, B, C, D, F, G, H, I, J, K, L, M
	Industrial premises		A, B, C, F, G, H, I, J, K, L
	Refurbishment and demolition survey:	Documented in-house procedure GDP1 and MGDP1	
	Domestic premises		A, B, C, D, F, G, H, I, J, K, L, M
	Commercial premises		A, B, C, D, F, G, H, I, J, K, L, M
	Industrial premises		A, B, C, F, G, H, I, J, K, L
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B, C, D, F, G, H, I, J, K, L, M

END