


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 0368 Type C Inspection Body <small>Accredited to ISO/IEC 17020:2012</small>	Tersus Consultancy Ltd Issue No: 035 Issue date: 21 October 2024	
	1st Floor Rainham House Manor Way Rainham Essex RM13 8RH	Contact: Mr C Simmonite Tel: +44 (0) 1909 560673 E-Mail: craig.simmonite@tersusgroup.co.uk Website: www.tersusgroup.co.uk

Inspection performed at/from the locations specified below

Locations covered by the organisation and their relevant activities

Location details		Activity	Location code
Address 1 st Floor Rainham House Manor Way Rainham Essex RM13 8RH	Local contact Mr T Rose Tel: +44 (0)1708 555705 Email: Trevor.Rose@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	A
Address Unit 1 Manor Drive Outgang Lane Dinnington Sheffield S25 3QU	Local contact Mrs G Purewal Tel: +44 (0)1909 560673 Email: Gurpreet.Purewal@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	B
Address Eurosafe House Tribune Way Centurion Park Clifton Moor York YO30 4RY	Local Contact Ms J Ormshaw Tel: +44 (0) 1904 691515 Email: Jen.Ormshaw@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	C
Address Red Mill House Red Mill Estate Wednesbury WS10 0NN	Local contact Mrs G Purewal Tel: +44 (0)121 244 1828 Email: gurpreet.Purewal@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	D



0368

Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Tersus Consultancy Ltd
Issue No: 035 Issue date: 21 October 2024

Inspection performed by the Organisation at/from the locations specified

Location details		Activity	Location code
Address Axs House Parc Nantgarw Cardiff CF15 7TW	Local contact Mr C Jones Tel: +44 (0) 1278 654 345 e-mail: Craig.Jones@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	F
Address Health Physics R S R L Building D60 Winfrith Dorchester DT2 8WQ	Local contact Mr D Evans Tel: +44 (0) 1278 654 345 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	G
Address 10 Rutherford Avenue Didcot OX11 0DF	Local contact Mr D Evans Tel: +44 (0) 1278 654 345 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	H
Address Hinkley Point A Power Station Bridgewater TE5 1YA	Local contact Mr D Evans Tel: +44 (0) 1278 654 345 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	I
Address Dungeness A Power Station Romney Marsh TN29 9PP	Local contact Mr D Evans Tel: +44 (0) 1797 343 217 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	J



0368

Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Tersus Consultancy Ltd
Issue No: 035 Issue date: 21 October 2024

Inspection performed by the Organisation at/from the locations specified

Location details		Activity	Location code
Address Oldbury Power Station Oldbury Naite Thornbury BS35 1RQ	Local contact Mr D Evans Tel: +44 (0) 7914 668960 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	K
Address Berkeley Power Station Berkerley GL13 9PA	Local contact Mr D Evans Tel: +44 (0) 7921 511 417 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	L
Address 2 Moor Lane Highburton Huddersfield HD8 0QS	Local contact Ms J Ormshaw Tel: +44 (0) 1484 604920 e-mail: Jen.Ormshaw@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying	M



0368

Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Tersus Consultancy Ltd
Issue No: 035 Issue date: 21 October 2024

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises		Health and Safety Executive Asbestos: The survey guide (HSG264, 2012)	A, B, C, D, F, G, H, I, J, K, L
	<u>Management survey:</u>	Documented in-house procedure GDP1 and MGDP1	
	Domestic premises		A, B, C, D, F, G, H, I, J, K, L, M
	Commercial premises		A, B, C, D, F, G, H, I, J, K, L, M
	Industrial premises		A, B, C, F, G, H, I, J, K, L
	<u>Refurbishment and demolition survey:</u>	Documented in-house procedure GDP1 and MGDP1	
	Domestic premises		A, B, C, D, F, G, H, I, J, K, L, M
	Commercial premises		A, B, C, D, F, G, H, I, J, K, L, M
	Industrial premises		A, B, C, F, G, H, I, J, K, L
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B, C, D, F, G, H, I, J, K, L, M
END			