


# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p><b>0368</b> <b>Type C</b> <b>Inspection Body</b></p> <p>Accredited to ISO/IEC 17020:2012</p>	<p><b>Tersus Consultancy Ltd</b></p> <p><b>Issue No: 036 Issue date: 21 August 2025</b></p>	
	<p><b>1<sup>st</sup> Floor Rainham House</b> <b>Manor Way</b> <b>Rainham</b> <b>Essex</b> <b>RM13 8RH</b></p>	<p><b>Contact: Mr C Simmonite</b> <b>Tel: +44 (0) 1909 560673</b> <b>E-Mail: craig.simmonite@tersusgroup.co.uk</b> <b>Website: www.tersusgroup.co.uk</b></p>
<p>Inspection performed at/from the locations specified below</p>		

### Locations covered by the organisation and their relevant activities

Location details	Activity	Location code
<p><b>Address</b> 1<sup>st</sup> Floor Rainham House Manor Way Rainham Essex RM13 8RH</p> <p><b>Local contact</b> Mr T Rose  Tel: +44 (0)1708 555705 Email: Trevor.Rose@tersusgroup.co.uk Website: www.tersusgroup.co.uk</p>	<p>Asbestos:  Surveying</p>	A
<p><b>Address</b> Unit 1 Manor Drive Outgang Lane Dinnington Sheffield S25 3QU</p> <p><b>Local contact</b> Mrs G Purewal  Tel: +44 (0)1909 560673 Email: Gurpreet.Purewal@tersusgroup.co.uk Website: www.tersusgroup.co.uk</p>	<p>Asbestos:  Surveying</p>	B
<p><b>Address</b> Eurosafe House Tribune Way Centurion Park Clifton Moor York YO30 4RY</p> <p><b>Local Contact</b> Ms J Ormshaw  Tel: +44 (0) 1904 691515 Email: Jen.Ormshaw@tersusgroup.co.uk Website: www.tersusgroup.co.uk</p>	<p>Asbestos:  Surveying</p>	C
<p><b>Address</b> Red Mill House Red Mill Estate Wednesbury WS10 0NN</p> <p><b>Local contact</b> Mrs G Purewal  Tel: +44 (0)121 244 1828 Email: gurpreet.Purewal@tersusgroup.co.uk Website: www.tersusgroup.co.uk</p>	<p>Asbestos:  Surveying</p>	D



0368

Type C  
Inspection Body

Accredited to  
ISO/IEC 17020:2012

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**Tersus Consultancy Ltd**  
**Issue No: 036 Issue date: 21 August 2025**

Inspection performed by the Organisation at/from the locations specified

Location details	Activity	Location code
<p><b>Address</b> Axys House Parc Nantgarw Cardiff CF15 7TW</p> <p><b>Local contact</b> Mr C Jones  Tel: +44 (0) 1278 654 345 e-mail: Craig.Jones@tersusgroup.co.uk Website: www.tersusgroup.co.uk</p>	<p>Asbestos:  Surveying</p>	F
<p><b>Address</b> Health Physics R S R L Building D60 Winfrith Dorchester DT2 8WQ</p> <p><b>Local contact</b> Mr D Evans  Tel: +44 (0) 1278 654 345 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk</p>	<p>Asbestos:  Surveying</p>	G
<p><b>Address</b> 10 Rutherford Avenue Didcot OX11 0DF</p> <p><b>Local contact</b> Mr D Evans  Tel: +44 (0) 1278 654 345 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk</p>	<p>Asbestos:  Surveying</p>	H
<p><b>Address</b> Hinkley Point A Power Station Bridgewater TA5 1YA</p> <p><b>Local contact</b> Mr D Evans  Tel: +44 (0) 1278 654 345 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk</p>	<p>Asbestos:  Surveying</p>	I
<p><b>Address</b> Dungeness A Power Station Romney Marsh TN29 9PP</p> <p><b>Local contact</b> Mr D Evans  Tel: +44 (0) 1797 343 217 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk</p>	<p>Asbestos:  Surveying</p>	J



0368

Type C  
Inspection Body

Accredited to  
ISO/IEC 17020:2012

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**Tersus Consultancy Ltd**  
**Issue No: 036 Issue date: 21 August 2025**

Inspection performed by the Organisation at/from the locations specified

Location details	Activity	Location code
<b>Address</b> Oldbury Power Station Oldbury Naite Thornbury BS35 1RQ	<b>Local contact</b> Mr D Evans  Tel: +44 (0) 7914 668960 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos:  Surveying  K
<b>Address</b> Berkeley Power Station Berkeley GL13 9PA	<b>Local contact</b> Mr D Evans  Tel: +44 (0) 7921 511 417 e-mail: David.Evans@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos:  Surveying  L
<b>Address</b> 2 Moor Lane Highburton Huddersfield HD8 0QS	<b>Local contact</b> Ms J Ormshaw  Tel: +44 (0) 1484 604920 e-mail: Jen.Ormshaw@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos:  Surveying  M



0368

Type C  
Inspection Body

Accredited to  
ISO/IEC 17020:2012

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**Tersus Consultancy Ltd**  
**Issue No: 036 Issue date: 21 August 2025**

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises		Health and Safety Executive Asbestos: The survey guide (HSG264, 2012)	A, B, C, D, F, G, H, I, J, K, L
	<u>Management survey:</u>	Documented in-house procedure GDP1 and MGDP1	
	Domestic premises		A, B, C, D, F, G, H, I, J, K, L, M
	Commercial premises		A, B, C, D, F, G, H, I, J, K, L, M
	Industrial premises		A, B, C, F, G, H, I, J, K, L
	<u>Refurbishment and demolition survey:</u>	Documented in-house procedure GDP1 and MGDP1	
	Domestic premises		A, B, C, D, F, G, H, I, J, K, L, M
	Commercial premises		A, B, C, D, F, G, H, I, J, K, L, M
	Industrial premises		A, B, C, F, G, H, I, J, K, L
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B, C, D, F, G, H, I, J, K, L, M
END			