# **Schedule of Accreditation**

issued by

# **United Kingdom Accreditation Service**

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK



1155

Accredited to ISO/IEC 17025:2017

# **Bradley Environmental Consultants Ltd**

Issue No: 035 Issue date: 12 August 2024

20 Stourbridge Road Contact: Mr R Bridgewater

Halesowen Tel: +44 (0)121 550 0224
West Midlands Fax: +44 (0)121 550 0641

B63 3US E-Mail: rbridgewater@bradley-enviro.co.uk

Website: www.bradley-enviro.co.uk

Testing performed by the Organisation at the locations specified below

#### Locations covered by the organisation and their relevant activities

#### **Laboratory locations:**

| Location details  |  | Activity   | Location code |
|---|--|--|---------------|
| Address<br>20 Stourbridge Road<br>Halesowen<br>West Midlands<br>B63 3US       | Contact: Mr R Bridgewater  Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk     | Health and Hygiene<br>Head Office<br>Asbestos – All Support<br>Functions   | A             |
| Address Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD            | Local contact Mr R Bridgewater  Tel: +44 (0)1924 274777  Fax: +44 (0)1924 283620  Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk | Health and Hygiene Asbestos – Support Functions:  • Contract Review • Scheduling • Personnel • Equipment • Measurement Traceability • Reporting      | В             |
| Address Constellation House Shorebury Point Amy Johnson Way Blackpool FY4 2RN | Local contact Mr R Bridgewater  Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk  | Health and Hygiene Asbestos – Support Functions:  • Contract Review  • Scheduling  • Personnel  • Equipment  • Measurement Traceability  • Reporting | C             |

Assessment Manager: EJ Page 1 of 3



1155 Accredited to ISO/IEC 17025:2017

### Schedule of Accreditation issued by

# United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

### **Bradley Environmental Consultants Ltd**

**Issue No:** 035 Issue date: 12 August 2024

#### Testing performed by the Organisation at the locations specified

| Location details   |  | Activity  | Location code |
|--|--|---|---------------|
| Address<br>85A Bowen Court<br>St Asaph Business Park<br>St Asaph<br>LL17 0JE | Local contact Mr R Bridgewater  Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk | Health and Hygiene Asbestos – Support Functions:  • Contract Review • Scheduling • Personnel • Equipment • Measurement Traceability • Reporting | D             |
| Address Unit 16 Geddes House Kirkton Road North Livingston EH54 6GU          | Local contact Mr R Bridgewater  Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk | Health and Hygiene Asbestos – Support Functions:  • Contract Review • Scheduling • Personnel • Equipment • Measurement Traceability • Reporting | F             |

#### Site activities performed away from the locations listed above:

| Location details            | Activity           | Location code |
|-----------------------------|--------------------|---------------|
| Client Premises             | Health and Hygiene | G             |
|                             |                    |               |
|                             |                    |               |
| Mobile Testing Laboratories | Health and Hygiene | Е             |
|                             |                    |               |

Assessment Manager: EJ Page 2 of 3



1155 Accredited to ISO/IEC 17025:2017

## **Schedule of Accreditation** issued by

# United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

## **Bradley Environmental Consultants Ltd**

**Issue No:** 035 Issue date: 12 August 2024

Testing performed by the Organisation at the locations specified

#### **DETAIL OF ACCREDITATION**

| Materials/Products tested  | Type of test/Properties measured/Range of measurement  | Standard specifications/<br>Equipment/Techniques used  | Location<br>Code |  |  |
|--|--|--|------------------|--|--|
|  | Health and Hygiene   | Health and Safety Executive -<br>Asbestos: The Analysts' Guide<br>(HSG 248) – 2021   |                  |  |  |
| ASBESTOS FIBRES IN AIR   | Sampling of air for fibre counting   | Documented In-House Method,<br>appendix 6, Quality Manual, based<br>on HSG 248   | A, B, C,<br>F, G |  |  |
|  | Fibre counting   | Documented In-House Method,<br>appendix 6m Quality Manual,<br>Membrane Filter Method using<br>Phase Contrast Microscopy (PCM)<br>based on HSG 248                        | A, B, C,<br>E, F |  |  |
|  | 4 Stage Clearance Process  | Documented In-House Method,<br>appendix 6, Quality Manual,<br>Membrane Filter Method using<br>Phase Contrast Microscopy (PCM)<br>based on HSG 248                        | A, B, C,<br>F, G |  |  |
| ASBESTOS IN BULK MATERIALS including materials and products suspected of containing asbestos | Sampling of bulk materials for subsequent identification of asbestos   | Documented In-House Method,<br>appendix 6, Quality Manual, based<br>on HSG 248   | A, B, C,<br>F, G |  |  |
|  | Identification of: Amosite Chrysotile Crocidolite Fibrous Actinolite Fibrous Anthophyllite Fibrous Tremolite | Documented In-House Method,<br>appendix 7, Quality Manual, using<br>stereo-microscopy, polarised light<br>optical microscopy and dispersion<br>staining based on HSG 248 | A, B, C,<br>D    |  |  |
| END  |  |  |                  |  |  |

Assessment Manager: EJ Page 3 of 3