


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

| | | |
|--|--|--|
|  27406 Accredited to ISO/IEC 17025:2017 | Nu-Cairn Ltd Issue No: 002 Issue date: 09 July 2025 | |
| | 1 Letham Road Houston Industrial Estate Livingston West Lothian EH54 5BY United Kingdom | Contact: Ms Lucy Garton Tel: +44 (0) 845 026 4680 E-Mail: info@nu-cairn.co.uk Website: www.nu-cairn.co.uk |
| Testing performed by the Organisation at the locations specified | | |

Locations covered by the organisation and their relevant activities

Site activities performed away from the locations listed above:

| Location details | Activity | Location code |
|---|----------------------------|---------------|
| All locations suitable for the activities listed Contact: Ms Lucy Garton | Testing Curtain walling | Site |



27406

Accredited to
ISO/IEC 17025:2017

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Nu-Cairn Ltd

Issue No: 002 **Issue date:** 09 July 2025

Testing performed by the Organisation at the locations specified

DETAIL OF ACCREDITATION

| Materials/Products tested | Type of test/Properties measured/Range of measurement | Standard specifications/ Equipment/Techniques used | Location Code |
|---|---|--|---------------|
| CURTAIN WALLING RAINScreens SLOPE GLAZING | Water Penetration – Hose Test | CWCT Standards for Systemised Building Envelopes and Test Methods for Building Envelopes, December 2006 Section 9 | Site |
| | Water Penetration – Spray Bar | Section 10 | Site |
| | Sparge Bar Test | NHBC Standards 2021 Section 6.9.18 | Site |
| WINDOWS and CURTAIN WALLING | Watertightness Site Test | BS EN 13051:2001 | Site |
| | Hose Test | NHBC Standards 2022 Section 6.9.17 | Site |
| END | | | |