

# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <b>27651</b> Accredited to <b>ISO/IEC 17025:2017</b>	<b>Trace Surveys Limited</b>	
	<b>Issue No:</b> 002	<b>Issue date:</b> 04 September 2025
	<b>Unit 4</b> Chapel Mill Road Kingsmill Business Park Kingston Upon Thames Surrey KT1 3GZ United Kingdom	<b>Contact:</b> Mr Tim Sanders <b>Tel:</b> +44 (0) 800 6120855 <b>E-Mail:</b> <a href="mailto:tim@tracesurveys.com">tim@tracesurveys.com</a> <b>Website:</b> <a href="https://www.tracesurveys.com">https://www.tracesurveys.com</a>
<b>Testing performed by the Organisation at the locations specified</b>		

### Locations covered by the organisation and their relevant activities

#### Site activities performed away from the locations listed above:

Location details	Activity	Location code
<b>Address</b> Unit 4 Chapel Mill Road Kingsmill Business Park Kingston Upon Thames Surrey KT1 3GZ United Kingdom <b>Local Contact:</b> Mr Tim Sanders	Management of the work only all site activities are performed away from the location listed above	N/A
<b>Address</b> All locations suitable for the activities listed <b>Local Contact:</b> Mr Tim Sanders	Testing: Watertightness curtain walling, windows, slope glazing	Site



27651

Accredited to  
ISO/IEC 17025:2017

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**Trace Surveys Limited**  
Issue No: 002 Issue date: 04 September 2025

Testing performed by the Organisation at the locations specified

DETAIL OF ACCREDITATION

Materials/Products tested	Type of test/Properties measured/Range of measurement	Standard specifications/ Equipment/Techniques used	Location Code
CURTAIN WALLING RAINSCREENS SLOPE GLAZING	<u>Performance Testing</u>	CWCT Standards for Systemised Building Envelopes and Test Methods for Building Envelopes, December 2006	
	Water Penetration – Hose Test	Section 9	Site
	Water Penetration – Spray Bar	Section 10	Site
	Sparge Bar Test	NHBC Standards 2025 Section 6.9.18	Site
WINDOWS and CURTAIN WALLING	Watertightness Site Test	BS EN 13051:2001	Site
	Hose Test	NHBC Standards 2025 Section 6.9.17	Site
END			