


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>4155 Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:2012</p>	Franks Portlock Consulting Limited Issue No: 017 Issue date: 13 February 2026	
	Unit 1a Hylton Park Sunderland SR5 3HD	Contact: Nicola Warburton Tel: +44 (0)191 419 3116 E-Mail: nicola.warburton@franksportlock.co.uk Website: www.franksportlock.co.uk
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code
<p>Address Franks Portlock Consulting Limited Unit 1a Hylton Park Sunderland SR5 3HD</p> <p>Local contact Mr P Franks Tel: +44 (0)191 419 3116 Email: phil.franks@franksportlock.co.uk Website: www.franksportlock.co.uk</p>	<p><u>Asbestos:</u> Surveying</p>	A
<p>Address Room 14, Rosyth Business Centre 16 Cromarty Campus Rosyth Europarc Rosyth Fife KY11 2WX</p> <p>Local contact Mr P Franks Tel: +44 (0)138 342 7321 Email: phil.franks@franksportlock.co.uk Website: www.franksportlock.co.uk</p>	<p><u>Asbestos:</u> Surveying</p>	B
<p>Address Site 2, 5A Sellafield Seascale Cumbria CA20 1PG</p> <p>Local contact Mr J New Tel: +44 (0)194 672 1760 Email: james.new@franksportlock.co.uk Website: www.franksportlock.co.uk</p>	<p><u>Asbestos:</u> Surveying</p>	C



4155

Type C
Inspection Body

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Franks Portlock Consulting Limited
Issue No: 017 Issue date: 13 February 2026

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012) Documented in-house procedure (Inspection Surveys Manual)	A, B
	Management survey: (commercial and industrial premises)	Documented in-house procedure (Inspection Surveys Manual)	C
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure (Inspection Surveys Manual)	A, B
	Refurbishment and demolition survey: (commercial and industrial premises)	Documented in-house procedure (Inspection Surveys Manual)	C
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method procedures Tech07 (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B
END			