Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, Middlesex, TW18 3HR



Locations covered by the organisation and their relevant activities

Laboratory locations:

Location details		Activity	Location code
Address 141 Heath Drive Chelmsford Essex CM2 9HQ	Local contact Mr P King Tel: +44 (0)1245 929029 Email: enquiries@kovaasbestos.co.uk	Health and Hygiene Asbestos – All Support Functions	A

Site activities performed away from the locations listed above:

Location details	Activity	Location code
Client Premises	Health and Hygiene	В
Mobile laboratory	Health and Hygiene	С

	Schedule of Accreditation issued by United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK
	Kova Asbestos Consultants Ltd
7736 Accredited to ISO/IEC 17025:2017	Issue No: 009 Issue date: 01 February 2022
	Testing performed by the Organisation at the locations specified

Materials/Products tested	Type of test/Properties measured/Range of measurement	Standard specifications/ Equipment/Techniques used	Location Code
	Health and Hygiene	Health and Safety Executive - Asbestos: The Analysts' Guide (HSG 248) – 2021	
ASBESTOS FIBRES IN AIR	Sampling of air for fibre counting	Documented In-House Method SAS 02 based on HSG 248	В
	Fibre counting	Documented In-House Method SAS 02, Membrane Filter Method using Phase Contrast Microscopy (PCM) based on HSG 248	A, B, C
	4 Stage Clearance Process	Documented In-House Method SAS 02, Membrane Filter Method using Phase Contrast Microscopy (PCM) based on HSG 248	В
ASBESTOS IN BULK MATERIALS including materials and products suspected of containing asbestos	Identification of: Amosite Chrysotile Crocidolite Fibrous Actinolite Fibrous Anthophyllite Fibrous Tremolite	Documented In-House Method SAS 04 using stereo-microscopy, polarised light optical microscopy and dispersion staining based on HSG 248	A
	END		1

DETAIL OF ACCREDITATION