Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK



Locations covered by the organisation and their relevant activities

Location details		Activity	Location code
Address The Haybarn Londonderry Farm Keynsham Road Willsbridge Bristol BS30 6EL	Local contact Contact: Mr Ben House Tel: +44 (0)117 932 2323 E-Mail: benhouse@casaenvironmental.co.uk Website: www.casaenvironmental.co.uk	Inspection Activities	A
Address Unit 110 Solent Business Centre Millbrook Road West Southampton S015 0HW	Local contact Contact: Mr Ben House Tel: +44 (0)117 932 2323 E-Mail: benhouse@casaenvironmental.co.uk Website: www.casaenvironmental.co.uk	Inspection Activities	В

	Schedule of Accreditation issued by United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK	
UKAS INSPECTION 7914 Type C Inspection Body	Casa Environmental Services Ltd Issue No: 007 Issue date: 27 March 2024	
Accredited to ISO/IEC 17020:2012		

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code	
Surveying for asbestos in premises		Health and Safety Executive Asbestos: The Survey Guide (HSG 264, 2012)		
	Management survey: (domestic & commercial premises)	Documented in-house procedure TP02 Asbestos Surveys	А, В	
	Refurbishment and demolition survey: (domestic & commercial premises)	Documented in-house procedure TP02 Asbestos Surveys	Α, Β	
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented in-house procedure TP02 Asbestos Surveys (based on guidance documented in Appendix 5 of HSG 227 (2004))	Α, Β	
END				

DETAIL OF ACCREDITATION