


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>7914 Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:2012</p>	<p>Casa Environmental Services Ltd</p> <p>Issue No: 008 Issue date: 23 December 2025</p>	
	<p>The Haybarn Londonderry Farm Keynsham Road Willsbridge Bristol BS30 6EL</p>	<p>Contact: Ben House Tel: +44 (0) 117 932 2323 E-Mail: benhouse@casaenvironmental.co.uk Website: www.casaenvironmental.co.uk</p>
<p>Inspection performed at/from the locations specified below</p>		

Locations covered by the organisation and their relevant activities

Location details		Activity	Location code
<p>Address</p> <p>The Haybarn Londonderry Farm Keynsham Road Willsbridge Bristol BS30 6EL</p>	<p>Local contact</p> <p>Contact: Jacqui Ward Tel: +44 (0) 117 932 2323 E-Mail: jacquiward@casaenvironmental.co.uk Website: www.casaenvironmental.co.uk</p>	<p>Inspection Activities</p>	<p>A</p>
<p>Address</p> <p>Unit 110 Solent Business Centre Millbrook Road West Southampton S015 0HW</p>	<p>Local contact</p> <p>Contact: Jake Kelly Tel: +44 (0) 117 932 2323 E-Mail: jakekelly@casaenvironmental.co.uk Website: www.casaenvironmental.co.uk</p>	<p>Inspection Activities</p>	<p>B</p>
<p>Address</p> <p>Suite 4b Ground Floor Unit A2 13 Barn Close Langage Business Park Plympton Plymouth PL7 5HQ</p>	<p>Local contact</p> <p>Contact: Alistair Williamson Tel: +44 (0) 175 298 7824 E-Mail: awilliamson@casaenvironmental.co.uk Website: www.casaenvironmental.co.uk</p>	<p>Inspection Activities</p>	<p>C</p>



7914

**Type C
Inspection Body**

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Casa Environmental Services Ltd
Issue No: 008 Issue date: 23 December 2025

Location details		Activity	Location code
Address Office 31 Stafford Business Village Dyson Way Staffordshire Business Technology Park Stafford ST18 0TW	Local contact Contact: Phil McLean Tel: +44 (0) 178 533 1410 E-Mail: philmclean@casaenvironmental.co.uk Website: www.casaenvironmental.co.uk	Inspection Activities	D



7914
Type C
Inspection Body
 Accredited to
 ISO/IEC 17020:2012

Schedule of Accreditation
 issued by
United Kingdom Accreditation Service
 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Casa Environmental Services Ltd
Issue No: 008 Issue date: 23 December 2025

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic & commercial premises)	Health and Safety Executive Asbestos: The Survey Guide (HSG 264, 2012) Documented in-house procedure TP02 Asbestos Surveys	A, B, C, D
	Refurbishment and demolition survey: (domestic & commercial premises)	Documented in-house procedure TP02 Asbestos Surveys	A, B, C, D
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented in-house procedure TP02 Asbestos Surveys (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B, C, D
END			