


# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p><b>9608</b></p> <p><b>Type C Inspection Body</b></p> <p>Accredited to ISO/IEC 17020:2012</p>	<p><b>Environmental and Site Safety Solutions Limited</b></p> <p><b>Issue No: 003    Issue date: 12 September 2025</b></p>	
	<p><b>Address</b></p> <p><b>Atlas House</b></p> <p><b>Suite 10 and associated rear outbuilding</b></p> <p><b>4 Sylvan Court</b></p> <p><b>Sylvan Way</b></p> <p><b>Basildon</b></p> <p><b>SS15 6TH</b></p> <p><b>United Kingdom</b></p>	<p><b>Contact: Mr Sia Shahnooshi</b></p> <p><b>Tel: +44 (0)1268 205 180</b></p> <p><b>E-Mail: sshahnooshi@esss.co.uk</b></p> <p><b>Website: www.esss.co.uk</b></p>
<p>Inspection performed at/from the above address only</p>		

### DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures
Surveying for Asbestos in Premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The Survey Guide (HSG 264, 2012)  Documented in house procedure SOP3
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in house procedure SOP3
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented in house procedure SOP3 (based on guidance documented in Appendix 5 of HSG 227 (2004))
	Priority assessment (domestic, commercial & industrial premises)	Documented in house procedure SOP3 (based on guidance documented in Health and Safety Executive guides HSG 264 (2012) and Appx. 3 of HSG 227 (2004))
END		