


# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <b>9982</b> <b>Type C</b> <b>Inspection Body</b>  Accredited to ISO/IEC 17020:2012	<b>EDP Health Safety and Environment Consultants Ltd</b>	
	<b>Issue No: 011    Issue date: 20 May 2026</b>	
<b>Unit 11B</b> <b>Waterside Court</b> <b>St Helens</b> <b>WA9 1UA</b>	<b>Contact: Mr Derek Todd</b> <b>Tel: +44 (0)1744 766 000</b> <b>E-Mail: derek.todd@edp-uk.com</b> <b>Website: www.edp-uk.com</b>	

Inspection performed at/from the locations specified below

### Locations covered by the organisation and their relevant activities

<u>Location details</u>	<u>Activity</u>	<u>Location code</u>
<b>Address</b> 65 Sussex Street Glasgow G41 1DX  <b>Local contact</b> Mr Steven Whiteford Tel: +44(0)845 644 5354 Email: enquiries@edp-uk.com  Website: www.edp-uk.com	Asbestos:  Surveying	A
<b>Address</b> Unit 11B Waterside Court St Helens WA9 1UA  <b>Local contact</b> Mr Mr Ben McPherson Tel: +44(0)845 644 5354 Email: enquiries@edp-uk.com  Website: www.edp-uk.com	Support functions: Administration	D



**9982**  
**Type C**  
**Inspection Body**

Accredited to  
 ISO/IEC 17020:2012

**Schedule of Accreditation**  
 issued by  
**United Kingdom Accreditation Service**  
 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**EDP Health Safety and Environment Consultants Ltd**  
**Issue No: 011 Issue date: 20 May 2026**

Inspection performed by the Organisation at/from the locations specified

**DETAIL OF ACCREDITATION**

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012)  Documented in-house procedure instruction manual IM No 5	A
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure instruction manual IM No 5	A
	Priority assessment: (domestic, commercial and industrial premises)	Documented in-house procedure instruction manual IM No 5 (based on guidance documented in Health and Safety Executive guides HSG 264 (2012) and Appx. 3 of HSG 227 (2004))	A
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method instruction manual IM No 5 (based on guidance documented in Appendix 5 of HSG 227 (2004))	A
END			