


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>UKAS TESTING 1155</p> <p>Accredited to ISO/IEC 17025:2017</p>	Bradley Environmental Consultants Ltd	
	Issue No: 033 Issue date: 08 July 2022	
	20 Stourbridge Road Halesowen West Midlands B63 3US	Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk
Testing performed by the Organisation at the locations specified below		

Locations covered by the organisation and their relevant activities

Laboratory locations:

Location details	Activity	Location code	
Address 20 Stourbridge Road Halesowen West Midlands B63 3US	Contact: Mr R Bridgewater Tel: +44 (0)121 550 0224 Fax: +44 (0)121 550 0641 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Health and Hygiene Head Office Asbestos – All Support Functions	A
Address Parkway House Wakefield Road Ossett West Yorkshire WF5 9JD	Local contact Mr R Bridgewater Tel: +44 (0)1924 274777 Fax: +44 (0)1924 283620 Email: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Health and Hygiene Asbestos – Support Functions: <ul style="list-style-type: none"> • <i>Contract Review</i> • <i>Scheduling</i> • <i>Personnel</i> • <i>Equipment</i> • <i>Measurement</i> • <i>Traceability</i> • <i>Reporting</i> 	B
Address Constellation House Shorebury Point Amy Johnson Way Blackpool FY4 2RN	Local contact Mr R Bridgewater Tel: +44 (0)1253 405396 Fax: +44 (0)1253 402426 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Health and Hygiene Asbestos – Support Functions: <ul style="list-style-type: none"> • <i>Contract Review</i> • <i>Scheduling</i> • <i>Personnel</i> • <i>Equipment</i> • <i>Measurement</i> • <i>Traceability</i> • <i>Reporting</i> 	C



1155
Accredited to
ISO/IEC 17025:2017

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd
Issue No: 033 Issue date: 08 July 2022

Testing performed by the Organisation at the locations specified

Location details	Activity	Location code	
Address 85A Bowen Court St Asaph Business Park St Asaph LL17 0JE	Local contact Mr R Bridgewater Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Health and Hygiene Asbestos – Support Functions: <ul style="list-style-type: none">• Contract Review• Scheduling• Personnel• Equipment• Measurement Traceability• Reporting	D
Address Unit 16 Geddes House Kirkton Road North Livingston EH54 6GU	Local contact Mr R Bridgewater Tel: +44 (0)1745 585587 Fax: +44 (0) 1745 584974 E-Mail: rbridgewater@bradley-enviro.co.uk Website: www.bradley-enviro.co.uk	Health and Hygiene Asbestos – Support Functions: <ul style="list-style-type: none">• Contract Review• Scheduling• Personnel• Equipment• Measurement Traceability• Reporting	F

Site activities performed away from the locations listed above:

Location details	Activity	Location code
Client Premises	Health and Hygiene	Halesowen - AS Ossett - BS Blackpool - CS St Asaph – DS Livingston - FS
Mobile Testing Laboratories	Health and Hygiene	E



1155
Accredited to
ISO/IEC 17025:2017

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Bradley Environmental Consultants Ltd
Issue No: 033 Issue date: 08 July 2022

Testing performed by the Organisation at the locations specified

DETAIL OF ACCREDITATION

Materials/Products tested	Type of test/Properties measured/Range of measurement	Standard specifications/ Equipment/Techniques used	Location Code
ASBESTOS FIBRES IN AIR	<u>Health and Hygiene</u>	Health and Safety Executive - Asbestos: The Analysts' Guide (HSG 248) – 2021	
	Sampling of air for fibre counting	Documented In-House Method, appendix 6, Quality Manual, based on HSG 248	AS, BS, CS, DS, E, FS
	Fibre counting	Documented In-House Method, appendix 6m Quality Manual, Membrane Filter Method using Phase Contrast Microscopy (PCM) based on HSG 248	A, B, C, D, F, AS, BS, CS, DS, E
ASBESTOS IN BULK MATERIALS including materials and products suspected of containing asbestos	4 Stage Clearance Process	Documented In-House Method, appendix 6, Quality Manual, Membrane Filter Method using Phase Contrast Microscopy (PCM) based on HSG 248	AS, BS, CS, DS, E, FS
	Sampling of bulk materials for subsequent identification of asbestos	Documented In-House Method, appendix 6, Quality Manual, based on HSG 248	AS, BS, CS, DS, E, FS
	Identification of: Amosite Chrysotile Crocidolite Fibrous Actinolite Fibrous Anthophyllite Fibrous Tremolite	Documented In-House Method, appendix 7, Quality Manual, using stereo-microscopy, polarised light optical microscopy and dispersion staining based on HSG 248	A, B, C, D, F
END			