

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>0223 Type C Inspection Body Accredited to ISO/IEC 17020:2012</p>	Eurosafe (UK) Ltd Issue No: 014 Issue date: 09 November 2016	
	Eurosafe House Centurion Park Tribune Way Clifton Moor York YO30 4RY	Contact: Mrs A Davies Tel: +44 (0)1904 691515 Fax: +44 (0)1904 691066 E-Mail: enquiries@eurosafeuk.co.uk Website: www.eurosafeuk.co.uk
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

<u>Location details</u>	<u>Activity</u>	<u>Location code</u>
Address Eurosafe House Centurion Park Tribune Way Clifton Moor York YO30 4RY Local contact: Mrs A Davies Tel: +44 (0)1904 691515 Fax: +44 (0)1904 691066 Email: eurosafe@eurosafeuk.co.uk	Surveying: Asbestos	A
Address 7 Horizon Court Audax Road Clifton Moor York YO30 4RB Local contact: Mrs A Davies Tel: +44 (0)1904 691515 Fax: +44 (0)1904 691066 Email: eurosafe@eurosafeuk.co.uk	Administrative Centre	A - Admin
Address The Old Vicarage Market Street Castle Donington DE74 2JB Local contact: Mrs A Davies Tel: +44 (0)1904 691515 Fax: +44 (0)1904 691066 Email: eurosafe@eurosafeuk.co.uk	Surveying: Asbestos	B



0223

**Type C
Inspection Body**

Accredited to
ISO/IEC 17020:2012

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Eurosafe (UK) Ltd

Issue No:014 Issue date: 09 November 2016

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for Asbestos in Premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos The survey guide; HSG 264, 2012 Documented In-House Inspection Method	A, B
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented In-House Inspection Method	A, B
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-house method based on guidance documented in Appendix 5 of HSG 227 (2004)	A, B
	Priority assessment: (domestic, commercial and industrial premises)	Documented In-House Inspection Method (based on guidance documented in Health and Safety Executive guides HSG 264 (2012) and Appx. 3 of HSG 227 (2004))	A, B
END			