


# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <b>0230</b> <b>Type C</b> <b>Inspection Body</b>  Accredited to ISO/IEC 17020:2012	<b>Tetra Tech Environment Planning Transport Limited</b>	
	Issue No: 019    Issue date: 22 April 2022	
	<b>11th Floor</b> <b>1 Angel Court</b> <b>London</b> <b>EC2R 7HJ</b>	<b>Contact: Mr D Gibb</b> <b>Tel: +44 (0)20 7090 7000</b> <b>Mob: +44(0)7940 560165</b> <b>E-Mail: duncan.gibb@tetrattech.com</b> <b>Website: https://www.tetrattechurope.com</b>
Inspection performed at/from the locations specified below		

### Locations covered by the organisation and their relevant activities

<u>Location details</u>	<u>Activity</u>	<u>Location code</u>
<b>Address</b> 11th Floor 1 Angel Court London EC2R 7HJ	<b>Local contact</b> Mr D Gibb  Tel: +44 (0)20 7090 7000 Mob: +44 (0)7040 560165 Email: duncan.gibb@tetrattech.com	<u>Asbestos:</u>  Surveying  A
<b>Address</b> 5 <sup>th</sup> Floor Sovereign Square 3 Sovereign Street Leeds LS1 4ER	<b>Local contact</b> Mr Nick Wilson  Tel: +44 113 382 1054 Mob: +44 7867 421 691 Email: nick.wilson@tetrattech.com	<u>Asbestos:</u>  Surveying  B



**0230**  
**Type C**  
**Inspection Body**

Accredited to  
ISO/IEC 17020:2012

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**Tetra Tech Environment Planning Transport Limited**  
**Issue No: 019 Issue date: 22 April 2022**

Inspection performed by the Organisation at/from the locations specified

#### DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for Asbestos in Premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012)  Documented in-house procedure 02	A, B
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure 02	A, B
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented in-house procedure 06 (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B
END			