


# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p><b>0265</b></p> <p><b>Type C Inspection Body</b></p> <p>Accredited to ISO/IEC 17020:2012</p>	<p><b>Enquin Environmental Limited</b></p> <p><b>Issue No: 103 Issue date: 20 June 2024</b></p>	
	<p><b>1 Ringside Business Centre</b> <b>Heol Y Rhosog</b> <b>Wentloog</b> <b>Cardiff</b> <b>CF3 2EW</b></p>	<p><b>Contact: Amie Charlton</b> <b>Tel: +44 (0)29 2053 5090</b> <b>E-Mail: acharlton@enquin.co.uk</b> <b>Website: www.enquin.co.uk</b></p>
<p>Inspection performed at/from the above address only</p>		

### DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures
Surveying for Asbestos in Premises	<p>Management survey: (domestic, commercial &amp; industrial premises)</p> <p>Refurbishment and demolition survey: (domestic, commercial &amp; industrial premises)</p> <p>Priority assessment: (domestic, commercial &amp; industrial premises)</p> <p>Reinspection of identified or suspected asbestos containing material in surveyed premises</p>	<p>Health and Safety Executive Asbestos: The Survey Guide (HSG 264, 2012)</p> <p>Documented In-House procedure as per Quality Control Manual, Section 4</p> <p>Documented In-House procedure as per Quality Control Manual, Section 4</p> <p>Documented In-House procedure as per Quality Control Manual, Section 4 (based on guidance documented in Health and Safety Executive guides HSG 264 (2012) and Appx. 3 of HSG 227 (2004))</p> <p>Documented In-House Method as per Quality Control Manual, Section 4 (based on guidance documented in Appendix 5 of HSG 227 (2004))</p>
<p>END</p>		