

# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p><b>0349</b> <b>Type C</b> <b>Inspection Body</b></p> <p>Accredited to ISO/IEC 17020:2012</p>	<b>G&amp;L Consultancy Limited</b>	
	<b>Issue No: 018    Issue date: 21 November 2019</b>	
<b>Unit 5a</b> <b>Chelston Business Park</b> <b>Castle Road</b> <b>Wellington</b> <b>Somerset</b> <b>TA21 9JQ</b>	<b>Contact: Mr D Alway</b> <b>Tel: +44 (0)1823 443898</b> <b>Fax: +44 (0)1823 443154</b> <b>E-Mail: darren.alway@gnl.org.uk</b> <b>Website: www.gnl.org.uk</b>	
Inspection performed at/from the locations specified below		

### Locations covered by the organisation and their relevant activities

<u>Location details</u>	<u>Activity</u>	<u>Location code</u>
<p><b><u>Address</u></b> 54A Huntly Road, Banbridge, Co. Down, Northern Ireland BT32 3UA</p> <p><b><u>Local contact</u></b> Mr A Lewis  Tel: +44 (0)2840 623566 Fax: +44 (0)2840 629217 Email: alan.lewis@gnl.org.uk Website: www.gnl.org.uk</p>	Asbestos:  Surveying (Office location)	
<p><b><u>Address</u></b> Unit 5a, Chelston Business Park Castle Road Wellington Somerset TA21 9JQ</p> <p><b><u>Local contact</u></b> Mr D Alway  Tel: +44 (0)1823 443898 Fax: +44 (0)1823 443154 Email: darren.alway@gnl.org.uk Website: www.gnl.org.uk</p>	Asbestos:  Surveying (Office location)	

### Site activities performed away from the locations listed above:

<u>Location details</u>	<u>Activity</u>	<u>Location code</u>
Premises including Domestic, Commercial and Industrial	Asbestos Surveying	C



**0349**  
**Type C**  
**Inspection Body**  
  
Accredited to  
ISO/IEC 17020:2012

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**G&L Consultancy Limited**  
**Issue No: 018 Issue date: 21 November 2019**

Inspection performed by the Organisation at/from the locations specified

**DETAIL OF ACCREDITATION**

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial & industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012)  Documented in-house procedure Inspection Method M5	C
	Refurbishment and demolition survey: (domestic, commercial & industrial premises)	Documented in-house procedure Inspection Method M5	C
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method M5 (based on guidance documented in Appendix 5 of HSG 227 (2004))	C
END			