


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p>0368 Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:2012</p>	Tersus Consultancy Ltd Issue No: 029 Issue date: 8 April 2021	
	1st Floor Rainham House Manor Way Rainham Essex RM13 8RH	Contact: Ms K Hukin Tel: +44 (0) 1909 560673 E-Mail: kylie.hukin@tersusgroup.co.uk Website: www.tersusgroup.co.uk

Inspection performed at/from the locations specified below

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code
Address 1 st Floor Rainham House Manor Way Rainham Essex RM13 8RH	Local contact Mr T Rose Tel: +44 (0)1708 555705 Email: trevor.rose@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying A
Address Unit 6 Carrera Court Dinnington Sheffield S25 2RG	Local contact Mr S Morley Tel: +44 (0)1909 560673 Email: simon.morley@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying B
Address Eurosafe House Tribune Way Centurion Park Clifton Moor York YO30 4RY	Local Contact Ms J Ormshaw Tel: +44 (0) 1904 691515 Email: Jen.Ormshaw@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying C
Address Red Mill House Red Mill Estate Wednesbury WS10 0NN	Local contact Miss G Cheema Tel: +44 (0)121 244 1828 Email: gurpreet.cheema@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying D
Address 1325 Park Avenue, Aztec West, Bristol BS32 4RX	Local contact Mr C Horton Tel: +44 (0) 1173 702506 Email: chris.horton@tersusgroup.co.uk Website: www.tersusgroup.co.uk	Asbestos: Surveying E



0368
 Type C
 Inspection Body
 Accredited to
 ISO/IEC 17020:2012

Schedule of Accreditation
 issued by
United Kingdom Accreditation Service
 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Tersus Consultancy Ltd
Issue No: 029 Issue date: 8 April 2021

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises		Health and Safety Executive Asbestos: The survey guide (HSG264, 2012)	A, B, C, D, E
	<u>Management survey:</u>	Documented in-house procedure	
	Domestic premises		A, B, C, D, E
	Commercial premises		A, B, C, D, E
	Industrial premises		A, B, C, E
	<u>Refurbishment and demolition survey:</u>	Documented in-house procedure	
	Domestic premises		A, B, C, D, E
	Commercial premises		A, B, C, D, E
	Industrial premises		A, B, C, E
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B, C, D, E
END			