


# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <p><b>0441</b> <b>Type C</b> <b>Inspection Body</b></p> <p>Accredited to ISO/IEC 17020:2012</p>	<p><b>Enviraz Surveys Limited</b> <b>(also trading as ESL)</b></p> <p><b>Issue No:</b> 008    <b>Issue date:</b> 04 October 2017</p>	
	<p><b>Curran House</b> 23-29 Kelvin Avenue Hillington Park Glasgow G52 4LT</p>	<p><b>Contact: Stephen Moffatt</b> <b>Tel: +44 (0)141 882 8440</b> <b>Fax: +44 (0)141 882 9528</b> <b>E-Mail: smoffatt@envirazsurveys.co.uk</b> <b>Website: www.envirazsurveys.co.uk</b></p>
<p>Inspection performed at/from the above address only</p>		

### DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures
Surveying for Asbestos in Premises	<p>Management survey: (domestic, commercial and industrial premises)</p> <p>Refurbishment and demolition survey: (domestic, commercial and industrial premises)</p> <p>Priority assessment: (domestic, commercial and industrial premises)</p> <p>Reinspection of identified or suspected asbestos containing material in surveyed premises</p>	<p>Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012)</p> <p>Documented In-House Inspection Method (PM1)</p> <p>Documented In-House Inspection Method (PM1)</p> <p>Documented in-house method (based on guidance documented in Health and Safety Executive guides HSG 264 (2012) and Appx. 3 of HSG 227 (2004))</p> <p>Documented In-House Method PM1 (based on guidance documented in Appendix 5 of HSG 227 (2004))</p>
<p>END</p>		