


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 4640 Type C Inspection Body Accredited to ISO/IEC 17020:2012	Omega Asbestos Consulting Limited	
	Issue No: 011 Issue date: 03 November 2022	
	First Floor Wellsprings Business Centre Durham Road West Bowburn Durham DH6 5AU	Contact: Mr G McKendrick Tel: +44 (0) 191 3770900 E-Mail: gary@omega-asbestos.co.uk Website: www.omega-asbestos.co.uk
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code	
Address First Floor Wellsprings Business Centre Durham Rd West Bowburn Durham DH6 5AU	Local contact Contact: Mr G McKendrick Tel: +44 (0) 191 3770900 E-Mail: gary@omega-asbestos.co.uk Website: www.omega-asbestos.co.uk	Inspection Activities: Health and Hygiene	A
Address Suite 14 Ripponden Business Park, Oldham Rd, Ripponden, West Yorkshire HX6 4FF	Local contact Contact: Lee Connor Tel: +44 (0)1422 340 340 E-Mail: leeconnor@omega- asbestos.co.uk Website: www.omega-asbestos.co.uk	Inspection Activities: Health and Hygiene	B

Location details	Activity	Location code
Premises including domestic, commercial and industrial	Health and Hygiene	A & B



4640
Type C
Inspection Body
 Accredited to
 ISO/IEC 17020:2012

Schedule of Accreditation
 issued by
United Kingdom Accreditation Service
 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

Omega Asbestos Consulting Limited
Issue No: 011 **Issue date:** 03 November 2022

Inspection performed at/from main address only

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for Asbestos in Premises		Health and Safety Executive Asbestos: The Survey Guide (HSG 264, 2012)	A & B
	Management survey: (domestic, commercial & industrial premises)	Documented in house Procedure Note 01	A & B
	Refurbishment and demolition survey: (domestic, commercial & industrial premises)	Documented in house Procedure Note 01	A & B
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented in house Procedure Note 01 (based on guidance documented in Appendix 5 of HSG 227 (2004))	A & B
	Priority assessment (domestic, commercial & industrial premises)	Documented in house Procedure Note 02 (based on guidance documented in Health and Safety Executive guides HSG 264 (2012) and Appx. 3 of HSG 227 (2004))	A & B
END			