

# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <b>8401</b> <b>Type C</b> <b>Inspection Body</b>  Accredited to ISO/IEC 17020:2012	<b>Inspectas Compliance Ltd</b>	
	Issue No: 008      Issue date: 24 July 2023	
	Atlas House 5-8 Bradford Road  Drighlington  BD11 1AS United Kingdom	<b>Contact: Mr Matthew Fahy</b> <b>Tel: +44 (0)8442 640094</b> <b>E-Mail: info@inspectas.co.uk</b> <b>Website: www.inspectas.co.uk</b>
<b>Inspection performed at/from the locations specified below</b>		

### Locations covered by the organisation and their relevant activities

Location details	Activity	Location code
<b>Address</b>  Atlas House 5-8 Bradford Road Drighlington BD11 1AS United Kingdom	<b>Local contact</b>  Contact: Mr Matthew Fahy Tel: +44 (0) 8442 640094 E-Mail: info@inspectas.co.uk Website: www.inspectas.co.uk	Asbestos:  Surveying  A
<b>Address</b>  Suite 19 Caxton Point Caxton Way Stevenage Hertfordshire SG1 2XU United Kingdom	<b>Local contact</b>  Contact: Mr Matthew Fahy Tel: +44 (0) 8442 640094 E-Mail: info@inspectas.co.uk Website: www.inspectas.co.uk	Asbestos:  Surveying  B



**8401  
Type C  
Inspection Body**

Accredited to  
ISO/IEC 17020:2012

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**Inspectas Compliance Ltd**  
**Issue No: 008    Issue date: 24 July 2023**

Inspection performed at/from the locations specified below

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises		Health and Safety Executive Asbestos: The survey guide (HSG264, 2012)	
	<u>Management survey:</u>	Documented in-house procedure	
	Domestic premises		A, B
	Commercial premises		A, B
	Industrial premises		A
	<u>Refurbishment and demolition surveys:</u>	Documented in-house procedure	
	Domestic premises		A, B
	Commercial premises		A, B
	Industrial premises		A
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method (based on guidance documented in Appendix 5 of HSG 227 (2004))	A, B
END			