


# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <b>9047</b> <b>Type C</b> <b>Inspection Body</b>  Accredited to ISO/IEC 17020:2012	<b>RPP Asbestos Services Ltd</b>	
	<b>Issue No: 004    Issue date: 23 February 2021</b>	
	<b>Blenwood Court</b> <b>451 Cleckheaton Road</b> <b>Low Moor</b> <b>Bradford</b> <b>BD12 0NY</b> <b>United Kingdom</b>	<b>Contact: Mr Kristian Bailey</b> <b>Tel: +44 (0)1274 693622</b> <b>E-Mail: K.Bailey@rppml.co.uk</b> <b>Website: www.rpp.co.uk</b>
Inspection performed at/from the above address only		

### DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures
Surveying for asbestos in premises	Management survey: (domestic, commercial, industrial premises)  Refurbishment and demolition survey: (domestic, commercial, industrial premises)  Reinspection of identified or suspected asbestos containing material in surveyed premises	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012)  Documented in-house procedure - RP&P ASL/P1 Asbestos Work Procedure  Documented in-house procedure - RP&P ASL/P1 Asbestos Work Procedure  Documented in-house procedure - RP&P ASL/P1 Asbestos Work Procedure (based on guidance documented in Appendix 5 of HSG 227 (2004))
END		