


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 9982 Type C Inspection Body Accredited to ISO/IEC 17020:2012	EDP Health Safety and Environment Consultants Ltd	
	Issue No: 010 Issue date: 09 August 2024	
	Unit 11B Waterside Court St Helens WA9 1UA	Contact: Mr Derek Todd Tel: +44 (0)1744 766 000 E-Mail: derek.todd@edp-uk.com Website: www.edp-uk.com
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

<u>Location details</u>	<u>Activity</u>	<u>Location code</u>
Address 9 Deer Park Avenue, Fairways Business Park, Livingston, EH54 8AF Local contact Mr Steven Whiteford Tel: +44(0)845 644 5354 Email: enquiries@edp-uk.com Website: www.edp-uk.com	Asbestos: Surveying	A
Address Unit 11B Waterside Court St Helens WA9 1UA Local contact Mr Mr Ben McPherson Tel: +44(0)845 644 5354 Email: enquiries@edp-uk.com Website: www.edp-uk.com	Support functions: Administration	D



9982
Type C
Inspection Body

Accredited to
 ISO/IEC 17020:2012

Schedule of Accreditation
 issued by
United Kingdom Accreditation Service
 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

EDP Health Safety and Environment Consultants Ltd
Issue No: 010 Issue date: 09 August 2024

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2012) Documented in-house procedure instruction manual IM No 5	A
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure instruction manual IM No 5	A
	Priority assessment: (domestic, commercial and industrial premises)	Documented in-house procedure instruction manual IM No 5 (based on guidance documented in Health and Safety Executive guides HSG 264 (2012) and Appx. 3 of HSG 227 (2004))	A
	Reinspection of identified or suspected asbestos containing material in surveyed premises	Documented In-House Method instruction manual IM No 5 (based on guidance documented in Appendix 5 of HSG 227 (2004))	A
END			